





Tsunami Impacts to Lifelines:

Learning about Tsunami Impacts on Infrastructure from Recent Events



Nick Horspool (GNS Science)
Stuart Fraser (World Bank)





Project Background

 Recognising the lack of information on tsunami impacts to lifelines ALG/WeLG commissioned study to summarise the available information

Project Aims:

- Document expected damage to the four lifelines sectors from tsunami
- Draw on experiences and learning's from previous events
- Develop recommendations for increasing lifelines resilience to tsunami





Information Sources

- Post-tsunami reconnaissance survey reports
- Scientific literature
- Reports published by lifeline operators
- Damage data from post-tsunami surveys
- First hand experience by report team:
 - 2010 Japan tsunami
 - 2015 Chile tsunami
- Variable quality of information:

| Lifeline Sector | Damage and Failure Models | Recovery Actions | Increasing Resilience | |
|--------------------|---------------------------|------------------|--------------------------|--|
| Water | | | | |
| Telecommunications | | | | |
| Transport | | | | |
| Energy | | | | |

Project Outputs

Report documenting, sector by sector:

- Likely damage and loss of functionality from tsunami
- Examples of <u>restoration and recovery</u> strategies during previous tsunami events
- Recommendations for <u>increasing resilience</u> from tsunami

Tsunami Damage Look-Up Tables, sector by sector:


- <u>Likelihood</u> of damage for different tsunami flow depth ranges (<0.5 m, 0.5 – 2 m, > 2m)
- Description of damage for each tsunami flow depth range

Tsunami Damage Look-Up Tables – Potable Water

| Lifeline Component | Flow Depth < 0.5m | | Flow Depth 0.5m – 2m | | Flow Depth >2m | | Information Quality | Sources |
|--------------------------------|-------------------|--|----------------------|---|----------------|---|------------------------|---|
| Drinking Water Pipes | Low | Minar siltation | Low | Scouring, exposure and floatation, debris strikes, damage at bridges | Medium | Scouring, exposure and floatation, debris strikes, damage at bridges | Medium | (American Society of Civil Engineers, 2005; Auckland Engineering Lifelines, 2014; Edwards, 2006; Eguchi et al., 2013; Francis, 2006; Ghobarah et al., 2006; Horspool & Fraser, 2015; Horspool et al., 2016; Kazama & Noda, 2012; Lekkas, 2011; Miyajima, 2014; Scawthorn et al., 2006; Tang & Edwards, 2012; Villholth & Neupane, 2011) |
| Wells | Medium | Salt water contamination of shallow wells | High | Salt water & sewage contamination, groundwater contamination, debris strikes to components | High | Salt water & sewage contamination, ground water & aquifer contamination, scour, debris strikes, components exposed & washed away | Low | (American Society of Civil Engineers, 2005; Robert; Bell et al., 2005; Chandrasekar & Ramesh, 2007; Edwards, 2006; Horspool & Fraser, 2015; Kim et al., 2014; Villholth & Neupane, 2011) |
| Storage | Low | Salt water contamination | Low-Medium | Salt water and sewage contamination, siltation, debris strikes to tanks & reservoir embarkments, low volume polyurethane tanks floated, scour of foundations, tilting of water towers | High | Salt water and sewage contamination, siltation, debris strikes to tanks & reservoir embankments, low volume polyurethane tanks floated, scour of foundations, tilting of water towers, floating of low volume concrete reservoirs, washout | Low | (American Society of Civil Engineers, 2005; Robert; Bell et al., 2005; Edwards, 2006; Francis, 2006; Horspool & Fraser, 2015; Villholth & Neupane, 2011) |
| Treatment & Pump Facilities | Low | Water damage to electrical & mechanical equipment | Medium- High | Water damage to structure interiors, salt & sewage contamination, equipment & machinery washed away, damage to electrical equipment | High | Water damage to interiors, salt & sewage contamination, collapse of structures, equipment & machinery washed away, damage to electrical equipment | Medium | (American Society of Civil Engineers, 2005; Robert; Bell et al., 2005; Edwards, 2006; Eguchi et al., 2013; Horspool et al., 2016; Scawthorn et al., 2006; Villholth & Neupane, 2011) |


Auckland's Tsunami Hazard


Maximum offshore tsunami height (above still water)



Auckland's Tsunami Hazard – Where Does it Come From?

1 in 500 Year: 3.5 m 1 in 2500 Year: 5.2 m









Transportation:

Roads and Bridges















Three Waters











Energy














Telecommunications



Key Findings Across Lifeline Sectors

- Relocation of assets outside of inundation zone if possible is the best mitigation option
- Electrical equipment is vulnerable and located near ground
- Back-up generators are often located on ground floors and also damaged
- Availability of spares critical to fast restoration of services
- Develop contingency plans for specific tsunami response
- Tsunami 'hotspots' for lifelines:
 - Coastal outflow sites and culverts → scour of coastal roads and loss of all below and above ground services
 - Bridges → scouring or washout causes loss of all colocated services on bridge
 - Coastal sites with multiple co-located lifelines (coastal road/rail/buried services or ports with fuel depots)

Now what?

- Learn and understand the potential impacts to your lifelines
 - Recovery planning
 - Strengthening network
- Undertake scenario impact modelling (RiskScape)
 - Damage state → functionality/levels of service
 - Economic losses → insurance
- Use as basis for more detailed work on impacts to specific lifelines

Nick Horspool – n.horspool @gns.cri.nz